

USDA-FOREST SERVICE

Index File No. Z-21

T 3S R. 31E

Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah County Umatilla

N.F. Umatilla State Oregon

Tract or Survey No. Sec 36 Cor. No. SW Cor

CORNER DIAGRAM

T3S R31E
S35 | S36



DESCRIBE CORNER MONUMENT FOUND

2 1/2" brass cap on 2 1/2" l. pipe protruding 10" from ground.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 10" dia W.Fir bears N38°E 8.0 ft dist tagged S38°W 8 ft dist-recent blaze
A 12" dia W.Fir brs N38½°W37.8 ft dist tagg S38°E 38ft dist-recent blaze.
Set a steel fence post with 54-4 sign 4 1/2 ft East of corner.

PHOTO IDENTIFICATION DATA

Photo No. 616140 780-5

Filed At. Umatilla Nat. Forest

Object Ident. Trees

Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

South on Yellow Jacket Road to road #5420, then South on road #5420 approximately 3.0 miles to cattleguard, then West along fence approx. 300 ft to fence corner E-W & N which is approximately 50 ft SW of corner, in timbered thicket on flat.

Signature

William R. Wells

Title

PLS 1106

Division

Headquarters

Date

October 4, 1982

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set steel fence post with 54-2 and 4 signs 4 1/2 ft. North of corner.
Surrounded monument with mound of earth. Cap marked:

T3S R31E
S.C.
S35 | S36
T4S R32E
OR PLS 1051
1977

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Blaze faces and 6" band around bearing trees are painted red.

Work Done By W.R. Wells Title Surveyor Date 10/4/82 State Registration No. PLS 1106
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Umatilla County Surveyor Office Date

REMARKS

Witnessed by: Leslie E. Wilson

Index File No.

Z-21

T.

3S

R.

31E

M.

W.M.

Tract or Surv. No.

Sec 36

Cor.

SW Cor

12

13

USDA-FOREST SERVICE

Index
File No. Z-21
T 3S R. R31E
Merid. W.M.


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah County Umatilla
N.F. Umatilla State Oregon

Tract or
Survey No. _____
Cor. No. _____ Sec. _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Not Found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No trace of BT's found.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is about 1150' east and 800' west of two main roads.
Falls on north side of N.F. boundary fence.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature

Barney B. Barber

Title
P. L. S.

Division

Headquarters

Date

11/8/77

7100-52-(3/68)


5

CORNER RECORD (PERPETUATION)

GPO 902-673

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

At surveyed point set 2½"x30" galvanized pipe with brass cap marked:
Set pipe 24" in the ground, with mound of stone around.



ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

From which: A fir 9" in dia. bears ^AN38°E, 7.9'; scribed T3S R31E S36BT. A fir 12" in dia. N38°W, 37.9'; scribed T3S R31E S35 BT. Placed 54-3s and 54-4s on BT's, brass washer on BT blaze, stamped PLS 1051. Placed 54-2 and 54-4 on fence post 4' east of corner. Painted 6" red bands and both blazes red.

10

Work Done By B.B. Barbour Title P.L.S. Date 11/8/77 State Registration No. OR PLS 1051
or Agency

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____ 11

REMARKS

Witnesses to the above corner: D.L. Landers
S. Nelson

12

Index File No. _____ T. _____ R. _____ M. _____ Tract or Surv. No. _____ Cor. _____ 13