

USDA-FOREST SERVICE

Index
File No. G-13


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

T 3S R. 33E R.D. Ukiah County _____

Merid. Will. N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None could be found

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND - A rotten douglas fir mostly rotted away was found. It has fallen over. I think it was a 28" fir bearing S 28 degrees E 82 links distance. Visible scribing on a piece of bark on the ground & some visible scribing on some bark on the fallen log. I painted both pieces of bark & attached a bearing tree tag to the log & also to the hardest part of the stump I could find. We were never really sure which tree this was. It could have been for section 9. Very little left of this corner.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By Tags & Paint

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

MLC

9-26-79

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

11

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

12

Index File No. T. R. M. Tract or Surv. No.

13