


Index
File No. P-1
T 3 S. R. 33 E
Merid. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____
R.D. UKIAH County UMATILLA
N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND
Stone 10" x 8" x 8", 8" above ground, marked $\frac{1}{4}$ and in good condition.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
Both BT's are down and rotting

(Over)

PHOTO IDENTIFICATION DATA
Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA
State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature Gary Collier

Title _____ Division _____ Headquarters Ukiah Date 6-8-73 7100-52-(3/68)

HL/878 OS

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Tagged new BT's
6" DBH Doug fir brs. N. 51° E. 33 ft.
18" DBH Doug fir brs. N. 39° W. 71 ft.

← What new B.T.'s? If non-Professional People (unlicensed) are establishing new B.T.'s they are not legal and serve only to Confuse later reestablishment.

Work Done By: _____ Title: _____ Date: _____ State Registration No. or Agency: J&H. 3/75

Certified Cor. Record Prepared? Yes No Filed At: _____ Date: _____

REMARKS