

Index File No. V-5
 T 3S R. 33E
 Merid. _____


CORNER RECORD (SEARCH)
 (Ref. FSM 7151.4)

R.D. Ukiah County _____
 N.F. Umatilla State _____

Tract or Survey No. _____
Umatilla
Oregon

Cor. No. V-5

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

One Douglas fir tree snag that was about 20' tall with good visible scribing on it bears N40°E 31 lks distance of which I cut down above the scribing to preserve the snag as long as possible. It is now about 5½ feet tall, has a 6" red band around it, with proper tags attached. At the approx. corner location, erected a steel post and attached two attention signs to it. No other evidence of the corner could be found.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature
MLC

Title
For Tech,

Division
USFS

Headquarters
Ukiah

Date
6/7/77

7100-52 (3/68)