

OR **ON PUBLIC LAND CORNER REPORT / RESTORATION REPO**
 Umatilla County Surveyor's Office

SECTION 25, 36	TOWNSHIP 4 North	RANGE 37 East
COUNTY: Umatilla		DATE September 15, 2007
CORNER DESIGNATION: W 1/16 corner common to 25, 36		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Renewed
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Surveyed In
		<input type="checkbox"/> Referenced Out
Previous Renewals / Surveys, etc. ODOT Contract #13025 drawing, and control network		
Monument(s) & Accessories Found: (Condition & Source) Found 1/2" iron rod in 2" iron pipe down 8" below gravel surface Accepted as 1/16 corner common to sections 25,36		
Monument Detail: 1/2" iron rod in 2" iron pipe	Sketch: 	
Monument Set (Procedures and Description): None		
New Accessories: None		
Location & Comments: 14.87 feet, BT tag on steel fence post measured from post to monument		Compass Declination: N 3 31 06 W
Firm / Agency B & D Surveys, LTD 2165 SE Dolphin Warrenton OR 97146		SURVEYOR'S SEAL
Party Chief Darryl Niemi PLS 1106		
Notes		
Witness Martin Foster		

V-22

07-294-R