


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T4N R38E

History of original corner establishment:
None. This corner was established
and monumented as part of this survey.



Description of corner evidence found:

Not applicable.

Description of monument and accessories established to perpetuate the original location of this corner:

At the position determined by survey, set a 2 1/2" by 30" aluminum pipe with 2 1/2" aluminum cap, 24" in the ground surrounded with a mound of earth and stone. Set steel fence post Southwest of corner and attached signs 54-2 and 54-4 to post. Monument cap is marked as shown in diagram.

New bearing trees:

A 20" ponderosa pine bears N 41 1/2° E, 18.4 feet, scribed COR 2, TR061411 BT-BT on double blaze.

An 11" Douglas fir bears S 67 1/2° E, 21.8 feet, scribed COR 2, TR061411 BT-BT on double blaze.

Painted face of blazes only on bearing trees. Did not place signs on bearing trees. Nailed brass washer stamped "PLS 1106" on bottom blaze of each bearing tree.

Compass declination: 18° East

Witnesses:

Jason Wells, LSIT
Mark Hammersla

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Renews 6-30-01

Office of... *Survey* ... County of... *Umatilla* ...
State of... *OR* ... I hereby certify that the within instrument was filed in this office
for record on the... day of... , 19....


..... by
(COUNTY OFFICIAL) (DEPUTY)

T4N R38
7

01-149-B

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
None. This corner was established
and monumented as part of this survey.



Description of corner evidence found:

Not applicable.

Description of monument and accessories established to perpetuate the original location of this corner:

At the position determined by survey, set a 2 1/2" by 30" aluminum pipe with 2 1/2" aluminum cap, 24" in the ground surrounded with a mound of earth and stone. Set steel fence post Southwest of corner and attached signs 54-2 and 54-4 to post. Monument cap is marked as shown in diagram.

New bearing trees:

A 20" ponderosa pine bears N 41 1/2° E, 18.4 feet, scribed COR 2, TR061411 BT-BT on double blaze.

An 11" Douglas fir bears S 67 1/2° E, 21.8 feet, scribed COR 2, TR061411 BT-BT on double blaze.

Painted face of blazes only on bearing trees. Did not place signs on bearing trees. Nailed brass washer stamped "PLS 1106" on bottom blaze of each bearing tree.

Compass declination: 18° East

Witnesses:
Jason Wells, LSIT
Mark Hammersla

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

Office of County Surveyor County of Umatilla
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the day of , 19

..... by
(COUNTY OFFICIAL) (DEPUTY)