

USDA-FOREST SERVICE

INDEX

FILE NO. V-3 CORNER RECORD (SEARCH) Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_  
 (Ref. FSM 7151.4)  
 T. 4 N R. 38 E R.D. Walla Walla County Umatilla  
 Merid. Willamette N.F. UMATILLA State Oregon 1

CORNER DIAGRAM 1 DESCRIBE CORNER MONUMENT FOUND  
 1 S30 1 Found standard 2 1/2" GLO brass cap stamped as shown in the diagram.  
 1 1/4 --- 1  
 N S31 1  
 1 1939 1 2

1 DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
 1 Found 16" double Western Larch stump with healed blaze N50°W, 188.1'. No evidence of other  
 PHOTO IDENTIFICATION DATA 1 BT's found.  
 Photo No. \_\_\_\_\_ 1  
 Filed At. \_\_\_\_\_ 1  
 Object Ident. \_\_\_\_\_ 1  
 Ident. By \_\_\_\_\_ 1  
 Signature 71 3

PLANE COORDINATE POSITION DATA 1 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
 State \_\_\_\_\_ Zone \_\_\_\_\_ 1 The corner may be reached by traveling Highway 204 west from the Tollgate Store 0.9 mile to  
 X \_\_\_\_\_ 1 the point where a point where the Highway makes a sharp left turn and a side road goes up a  
 Y \_\_\_\_\_ 1 a steep hill through an opening to the east. The corner is straight up this steep hill 400'  
 Etab. By \_\_\_\_\_ 1 in the opening near an electrical power transformer.  
 Agency 81 4

Signature Title Division Headquarters Date FS-7100-52 (3/68)  
 Surveyor Pendleton, OR 9-04-95 5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Monument in good condition.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set new bearing trees.

A 14" dbh Western Larch bears S14°46'E, 142.9' scribed 1/4 S31 BT.

A 7" dbh White Fir bears S16°57'W, 96.1' scribed 1/4 S31 BT.

Scribed and signed a short power pole near the corner N56°47'W, 4.6'.

Set a 5/8" x 24" rebar with aluminum cap N45°37'E, 103.1' stamped with BO COR and bearing and distance to corner.

A brass washer stamped ORLS 852 and WALS 13922 is nailed between the letters B and T on each tree with a brass screw.

All the BT's have BT and LSW signs attached. A red band is painted around each tree at chest height.

10

Work Done By David L. Haddock Title Land Surveyor Date 8-17-95 State Registration No. \_\_\_\_\_  
Certified Cor. Record Prepared? x Yes No Filed At: Umatilla County Surveyor Date 9-95 PLS 852 11

REMARKS

12

Index File No. V-3 T. 4 N. R. 38 E. M. Willamette Tract or Surv. No. \_\_\_\_\_ Cor. \_\_\_\_\_ 13

Index File No. V-3

**CORNER RECORD (SEARCH)**  
(Ref. FSM 7151.4)

Tract or Survey No. \_\_\_\_\_ Cor. No. V-3


T 4 N R. 38 E

R.D. Walla Walla County \_\_\_\_\_

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Brass Cap. Size:  $2\frac{1}{2}$ ".  
Good condition. Markings:  $\frac{1}{4}$  S 30  
S 31 1939

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Northwest quadrant, tamarack blaze closed.  
Southeast quadrant, 2' stump scribed: S 31, B.T.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

Signature B. Moore Title Engineering Technician Division \_\_\_\_\_ Headquarters S. O. Date August 1975 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13