

USDA-FOREST SERVICE

Index

File No. W-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor.

No. 1/16

T 4N R. 38E

R.D.

Walla Walla

County

Umatilla

Merid. W5W

N.F.

Umatilla

State

OR

CORNER DIAGRAM



N 1/16

533 / 534

1985

LS 951

DESCRIBE CORNER MONUMENT FOUND

1'4" I Bur lies N80°20'E 5.36 ft from Cor.

No Record Pd.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Jct Rd # 6401 with # 64

Go East on # 64 10 mile.

Corner is 130' south of 54-6

Sign on tree

Signature

Title

Division

Headquarters

Date

7100-52 (3. 68)

*J. Dennis Chavez*

LS 951

Hermiston

7/19/85

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

Set 2"x30" Iron Pipe 29" in ground with Brass cap stamped as diagram

Drove steel fence post 4' North & attached 54-9 sign.

**ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

a 10" spruce bears N  $0^{\circ}52'$  W 19.0 ft. scribed N  $1^{\circ}10'$  S 33 BT  
 a 1 1/4" Iron Bar Bears N  $88^{\circ}20'$  E 5.36 ft. Behind which I drove a steel fence post & attached 54-3-54-9 signs. Attached Alum. tag # 951 to Bar. I nailed alum. tag stamped 951 to Btm Blaze & painted Blaze Red Painted Red Band around BT & nailed 54-3 & 54-9 signs on. 10

Work Done By G. D. Edwards Title LS Date 7/19/85 State Registration No. OR 951  
 or Agency  
 Certified Cor. Record Prepared?  Yes  No Filed At: Pendleton, OR Date 7/19/85 11

REMARKS