

USDA-FOREST SERVICE

Index

File No.

Z-3

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

1/4

T 4N R. 38E

R.D. Walla Walla County UMATILLA

Merid. Willamette

N.F. UMATILLA State OREGON

CORNER DIAGRAM

T4N R38E



1/4 S31

T3N

RPE 2808

1976

DESCRIBE CORNER MONUMENT FOUND

2 1/2" Brass Cap on 1 1/2" Galvanized Pipe

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

14" white fir N 73°W 33.0'

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

South 0.7 mi from Haney Viewpoint on Hwy 204 15' west of road

Signature  
David H. Kulber

Title PLS 933 Division

Headquarters

Date 1/82

7100-52-(3-68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NONE

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Painted Trees

7" Spruce N 87° E 60.0 Feet with B.T. and Attention Signs

Work Done By D Krumbew Title County Surveyor Date 11-3-82 State Registration No. PLS 933  
or Agency

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA COUNTY Date 11/83

REMARKS

Index File No. Z-3 T. 4N R. 38E M. Willamette Tract or Surv. No.

Cor. 1/4

Index File No. Z 3  
 T 4 N R. 38 E  
 Merid. Willamette


**CORNER RECORD (SEARCH)**

(Ref. FSM 7151.4)

R.D. Walla Walla County Umatilla  
 N.F. Umatilla State Oregon

Tract or Survey No. \_\_\_\_\_  
 Cor. No. Z 3

**CORNER DIAGRAM**



**DESCRIBE CORNER MONUMENT FOUND**

NONE

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**

NONE

**PHOTO IDENTIFICATION DATA**

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
*Signature*

**DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER**

0.7 miles southerly on Haney viewpoint road. Corner is on west side of road 20 feet.

**PLANE COORDINATE POSITION DATA**

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estob. By \_\_\_\_\_  
*Agency*

*James D. Hanley*

Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_  
 RPE 2808 7/14/76 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2½" brass cap on a 2" iron pipe 31 " long in earth and rock mound 6" above grd. with a 6' steel fence post 5' east with sign 54-4 and 54-2 attached. Also a 6' steel fence post 3' south with sign 54-2 attached.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A fir 12" diam. bears N. 73° W., 33.0 ft. dist. marked 1/4 S 31 BT with sign 54-3 attached 6" below a band of red paint and a brass washer marked RPE 2808 nailed flush with BT blaze.

10

Work Done By. James D. Hanley Title Engineer n Date 7/22/76 State Registration No. ORPE 2808  
or Agency

Certified Cor. Record Prepared ? Yes ~~NO~~ Filed At: Pendleton, Oregon Date 8/ /76

11

REMARKS

12

Index File No. Z 3 T. 4 N R. 38 E M. W Tract or Surv. No. Cor. 13