

Index File No. X 25

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. X 25

T 4S R. 33KE


R.D. UKIAH County UMATILLA

Merid. WNM

N.F. UMATILLA State ORE

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND NW BT A 90" PINE N40W, 71.9 FT.
VIGOROUS, OPENED, SCRIBES VISIBLE
NE BT WAS IN THE ROAD AND IS DESTROYED.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature D.J. Driffold Title SURVEYOR Division _____ Headquarters _____ Date 12/75 7100-52 (3/68)

(21)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 30" IRON PIPE WITH BRASS CAP
AT RECORD BNS AND DIST. FROM BT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

NEW BT:

A 2 1/2" PINE N74E, 77.4 FT.

10

Work Done By D.I. GRIFFITH Title SURVEYOR Date 12/75 State Registration No. ORE PLS644
or Agency

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA CO. CT. MO Date 12/75

11

REMARKS

SEE MAP OR SURVEY DATED DEC. 1975

12

Index File No. X25 T. 45

R. 33 1/2 E WM.

Tract or Surv. No.

Cor. X 25 13