

Index File No. V-3

**CORNER RECORD (SEARCH)**

Tract or

Cor.

T 4S R. 34E

(Ref. FSM 7151.4)

Survey No. \_\_\_\_\_


No. \_\_\_\_\_

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE N.F. UMATILLA State OREGON

**CORNER DIAGRAM**

**DESCRIBE CORNER MONUMENT FOUND**



MATERIAL: STONE, SIZE: 18x10x6 HEIGHT ABOVE GROUND: ALL, CONDITION: GOOD, MARKINGS:  $\frac{1}{4}$ .

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**

EARLIER SEARCH TURNED UP NOTHING. LATER SEARCH WE FOUND STONE. THIS STONE WAS IN EDGE OF OLD LOGGING ROAD AND WAS 95% BURIED IN THE EDGE OF SAID ROAD.

**PHOTO IDENTIFICATION DATA**

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
CORNER WAS LATER FOUND BY PACING FROM OLD METAL TAG FOUND ON WEST SIDE OF 18" PINE TREE APPROXIMATELY  $7\frac{1}{2}$  CHAINS WEST OF APPROXIMATE  $\frac{1}{4}$  CORNER 30&31. CORNER HAS UNDOUBTEDLY BEEN MOVED BY PREVIOUS LOGGING ACTIVITY. A METAL POST WAS SET AT STONE AND METAL ATTENTION SIGN WAS ATTACHED TO POST. BEARING TREES ARE ASSUMED LOST BY ROAD THAT WAS CONSTRUCTED. STONE WAS PAINTED RED EXCEPT FOR THE CHISLED  $\frac{1}{4}$ .

**PLANE COORDINATE POSITION DATA**

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

*CJC MLC* *Yorestrytech* *USFS* *Ukiah* *10/26/74* *7100-52-(3/68)*

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

**ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

**REMARKS**

Index File No. / T. R. M. Tract or Surv. No. Cor.