

OREGON CORNER RESTORATION FORM

Section 15 Township 5N Range 28E

L-13

County UMATILLA Date 11/95

CORNER DESIGNATION

W. $\frac{1}{4}$ Cor.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. ORIG. SUR. BY DAVENPORT in 1861 Contrat #101
DEPENDENT SURVEY BY ME IN 1988 Co Contrat 1987-1

Monument(s) & Accessories Found: (Condition and Source)

NOTHING FOUND

Monument Detail

Sketch



Monument Set (Procedures and Description)

By Retracing my 1988 survey I set a 1"x30" I. Pipe
with a 2 3/8" Brass Cap stamped as above

SEE MY SURVEY FOR COLUCCIO

New Accessories

A 5/8"x30" rebar with 2" Alum Cap Bears EAST 13.95 FT.
" " " " " " " " N54°24'W 27.83 FT.
Alum tag #951 in 20" Mulberry tree Bears S64°48'30"W 101.35 FT.
" " " in P. Pole Bears S70°43'E 108.60 FT.

Location & Comments

From Intersection of Compass Declination
US HWY # 730 with Firm/Agency EDWARDS
LIND RD. go South SURVEYING
on LIND RD. 0.17 Mile Address P.O. BOX 763
HERMISTON, OR 97838
Party Chief D. Edwards
Notes
Witness J. Coppock

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

G. Dennis Edwards

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RENEWS 12/31/95

09-40-A