

USDA-FOREST SERVICE

Index File No. M-9

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____


T 5N R. 38E

R.D. WALLA WALLA County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STEEL FENCE POST IN M.D.S, WITH A BLM TAG MARKED: "BLM 1/16 CORNER LOCATED BY STAFF COMPASS" "1973"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

STEEL FENCE POST BEARS 56°08'E, 46.9 FT. FROM CORNER POINT AS DETERMINED BY SURVEY

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

Signature
P. TOMKINS

Title
PLS 2360

Division

Headquarters

Date
8/94

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ALUM. CAP ON RE-BAR

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" FIR N 85W, 12 1/2 FT

10

Work Done By P. TOMKINS Title _____ Date _____ State Registration No. or Agency 2360

Certified Cor. Record Prepared? Yes No _____ Filed At: _____ Date _____

11

REMARKS

12

Index File No. M-9 T. 5N R. 38E M. _____ Tract or Surv. No. _____ Cor. _____

13