

Index
File No. N-11
T 5 S. R. 30 E.
Merid. Willamette

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. _____

R.D. Ukiah County Umatilla
N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Markings: Area disturbed by logging.

Monumented By BLM, 1978

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2

42" pine blazed on east side. 1 blaze 1' above ground, 1 blaze 4' above ground. B.T. tag on east side. Warning tag, 54-4 on west side. Blazes closed over. Tree is in bottom of shallow swale. There is a 30" pine at about the same bearing and distance as the other B.T. listed in GLO Notes, but no evidence of blazing. The tree shows evidence of rapid growth. I hacked off some bark looking for scar but found nothing. No other trees in immed. vicinity.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From New Western Route Rd., travel southerly on Road S-420 for about 1.9 miles to a point about 1000' N. of Sec. line between Sec. 9 & 16. Turn west on logging road which meanders W. and S. Travel about 1.9 mi. to road forks. (I placed 2 location posters on approx. section line at this point, 1 for 1/4 corner East and 1 for sec. corner W. Follow ribbons E. to 1/4 cor., approx. 1200", W. to Sec. corner approx. 1400'. (Dist. on location posters - est.)

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

T.G. Holloman

Signature Title Division Headquarters Date
T.G. Holloman Engr. Tech. Umatilla N.F. - S.O. 9-19-73 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I hung red and white-striped ribbon along south line of Section 16
(meandering) from Road S-420 west to Section Corner. (16-17-20-21)

Probably satisfactory for monumentation.

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. *N-11* T. R. M. Tract or Surv. No. Cor. _____


Index File No. N-11
T 5 S. R. 30 E
Merid. Will.

CORNER RECORD (SEARCH)

Tract or Survey No. _____
Cor. No. _____

R.D. UKIAH County Umatilla
N.F. Umatilla State ORC.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Basalt stone 13"x10"x6", 6" above ground
and in good condition, marked 1/4
Monumented by BLM, 1978

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

34" D.B.H. Pond. Pine in fair vigor

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

Signature

Don McCullough

Title

Forestry Tech.

Division

Headquarters

UKIAH

Date

9-31-66

7100-52

REV. '65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. *N-11* T. R. M. Tract or Surv. No. Cor. _____