

Index File No. T-25


CORNER RECORD (SEARCH) Tract or Survey No.

Cor. No. T-25 <sup>27</sup> <sup>9</sup>

T 5S R. 29E  
Merid. Willamette

R.D. Ukiah County Morrow  
N.F. Umatilla State Oregon

CORNER DIAGRAM



~~DESCRIBE CORNER MONUMENT FOUND~~ *Original notes*  
BT PP (fallen over) S60E 34'  
DF 25" dia. BH N44W 77'

*Monumented by BLM in 1978*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
a sec. line board on the road between Divide Well and Matlock Water Hole, thus north 650' to a pile of rock that indicated the corner.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

Signature L. Waid Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date 1962

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

12

Index File No. T-25 T. R. M. Tract or Surv. No. Cor. 13