

USDA-FOREST SERVICE

Index

File No.

X-11

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

T 5S

R. 32E

R.D.

UKIAH

County

UMATILLA

Merid.

WILLAMETTE

N.F.

UMATILLA

State

OREGON

CORNER DIAGRAM

T 5 S R 32 E

C 1/4 S 33

1968



DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set,
2 1/2 ins. diam., in a mound of
stone, 3 ft. base, to top,
with brass cap mkd.

U.S. Dept. of The Interior
Bureau of Land Management

T 5 S R 32 E

C 1/4 S 33

1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Ponderosa Pine, 10 ins. diam., bears N. 75° E., 227 lks. dist.,
A Ponderosa Pine, 11 ins. diam., bears S. 70° W., 50 lks. dist.,
Both BT's found to be in good condition.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Title

Division

Headquarters

Date

7100-52-(3,68)

LS 1099

9-17-84

Ray J. Langley

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By Gary Langtitz Title LS 1099 Date 8-84 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. X-11 T. 55 R. 32E M. WILLAMETTE Tract or Surv. No. _____ Cor. _____