

USDA-FOREST SERVICE

Index  
File No. X-17  
T 55 R. 32E  
Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah County Umatilla  
N.F. Umatilla State Oregon

Tract or  
Survey No. \_\_\_\_\_  
Cor.  
No. \_\_\_\_\_

CORNER DIAGRAM



T 5 S R 32 E  
S 34 | S 35  
1968

DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set,  
2½ ins. diam., 4 inches above  
ground, with brass cap mkd,

U.S. Dept. of Interior  
Bureau of Land Management  
T 5 S R 32 E

S 34 | S 35  
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A white fir, 16 ins. diam., bears S. 35½° E., 18½ lks, dist.,  
A white fir, 10 ins. diam., bears N. 20° W., 59½ lks. dist.,  
A larch snag, 16 ins. diam., bears S. 45° W., 10 lks. dist.,  
with scribe marks ¼ S visible on partially opened blaze.  
BT's are alive and well-healed.

PHOTO IDENTIFICATION DATA

Photo No. Z80-233  
Filed At. UMATILLA NAT. FOR.  
Object Ident. DIRECT  
Ident. By G. J. Haight  
*signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_

*Signature*  
Gary J. Haight  
Agency

Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date 9-17-84  
LS 1099 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By. Gary Langlitz Title Land Surveyor Date 8-84 State Registration No. 1099  
or Agency

Certified Cor. Record Prepared? Yes  No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. X-17 T. 5S R. 32E M. Willamette Tract or Surv. No. \_\_\_\_\_ Cor. \_\_\_\_\_

Index File No. X-17

CORNER RECORD (SEARCH) Tract or Survey No. \_\_\_\_\_

LL 7  
Cor. No. X-17

T 5S R. 32E


R.D. Ilkiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM

~~DESCRIBE CORNER MONUMENT FOUND~~ *Original notes*



Corner is a pine post from which a tam. 8" DBH bears east 16lks  
tam. 10"DBH " S45W 10lks  
● *See mun. file*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2

Sec. 34BT 16" WL, medium vigor, placed forms 54-3, 54-4 painted red band around tree  
Sec. 35BT, dead and down, scribing still visible, painted red.

PHOTO IDENTIFICATION DATA 6

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature* 7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 3

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency* 8

Signature \_\_\_\_\_ Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_ 4

*15/ Kenneth Johnson*

*FORESTER*

*7-16-65*

7100-52  
REV. 65 5

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

9

**ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

**REMARKS**

12

Index File No. X-17 T. R. M. Tract or Surv. No. Cor. 13