

USDA-FOREST SERVICE

Index

File No. C-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 58 R. 33E

R.D. Ukiah

County Umatilla

Merid. W.M.

N.F. Umatilla

State Or.

CORNER DIAGRAM



0 1/2 S 2

DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls in open pasture. 6' steel fence post with "Land Survey Monument" sign is visible from CE 1/16 cor.

Signature

F.L. Munro

Title

L.S.

Division

Headquarters

Date

9/26/84

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" x 30" alum. pipe with 3" alum. cap mkd:

T58 R33E
 0 1/4 S2
 PLS 1832
 1984

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5/8" x 30" iron rod (Rebar) with 1 1/4" yellow plastic cap mkd: PLS 1832
 bears S31 1/4° E, 14.22 ft..

5/8" x 30" iron rod (Rebar) with 1 7/8" alum. cap mkd: PLS 1832
 bears N58 1/2° E, 11.35 ft..

RM



Work Done By F.S. Munro Title L.S. Date 9/13/84 State Registration No. 1832
 or Agency
 Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Surveyor Date _____

REMARKS

Index File No. G-19 T. 58 R. 33E M. W.M. Tract or Surv. No. _____ Cor. _____