

USDA-FOREST SERVICE

Index  
File No. D-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_ Cor.  
No. \_\_\_\_\_


T 58 R. 33E

R.D. Ukiah County Umatilla

Merid. W.M.

N.F. Umatilla State Or.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls on NW slope approx. 50' E of small draw. From SW1/16 cor., visible from 036 rd., go 1/4 mi. E. along posted property line.

*Signature*  
*F. J. Murray*

Title  
L.S.

Division

Headquarters

Date

9/26/84

7100-52-(3/68)

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

2 1/2" x 30" alum. pipe with 3" alum. cap mkd:

S1/16 | C | S2  
| O |

Built stone mound around cor. monument.

PLS 1832  
1984

**ACCESSORIES : DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

Tamarack, 6", S77 1/4° W, 31.8 ft.

D. fir, 6", S6-3/4° W, 14.0 ft.

BTs have reqd. paint, tags & signs.

Work Done By F.S. Muaro Title L.S. Date 9/15/84 State Registration No. 1832  
Or Agency

Certified Cor. Record Prepared? Yes  No Filed At: Imatilla Co., Surveyor Date

REMARKS

Index File No. D-19 T. 58 R. 33E M. W.M. Tract or Surv. No. Cor.

9

10

11

12

13