

USDA-FOREST SERVICE

Index

File No. D-20

T 58 R. 33E

Merid. W.M.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah

N.F. Umatilla

Tract or

Survey No. _____

Cor.

No. _____

County Umatilla

State Or.

CORNER DIAGRAM



SE1/16 S2

DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls on NW slope in scattered timber. From SW1/16 cor. visible from 036 rd. go E. $\frac{1}{2}$ mi. along posted property line.

Signature

R. Munro

Title

L.S.

Division

Headquarters

Date

9/26/84

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2½" x 30" alum pipe with 3" alum. cap mkd:

821/16 S2
PLS 1832
1984

Built stone mound around the monument.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

D. fir, 6", S69-3/4°W, 18.0 ft.

P. pine, 6", S9°W, 16.4 ft.

BTs have reqd. paint, tags & signs.

Work Done By F.S. Munro Title L.S. Date 9/13/82 State Registration No. 1832
or Agency

Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Surveyor Date

REMARKS

Index File No. D-20 T. 5S R. 33E M. W.M. Tract or Surv. No. Cor.