


CERTIFIED RECORD OF LAND CORNER MONUMENTATION


Index File No. C-13

History of original corner establishment:
No corner was originally set.



Description of corner evidence found:

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:
Set pipe 16" in ground to rock with mound of stone to cap.



Bearing Trees:
A Ponderosa Pine 13" dia. bears N45°E, 110.8 ft., scribed 1/4 S3BT
A Douglas Fir 9" dia. bears S79°E, 181.1 ft., scribed 1/4 S3BT

Attached 54-3 and 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-2, 54-4, and 54-9 signs to metal post 6 ft. north of corner.

I hereby certify the above corner monument was established as herein described on July 9, 1980.

Witnesses: R. Orton
L. Huntsman
D. Allen



Office of..... County Surveyor..... County of..... Umatilla
Oregon
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of..... 1980
..... by.....
(COUNTY OFFICIAL) (DEPUTY)