

OREGON CORNER RESTORATION FORM

Section: 36

Township: 6 North

Range: 37 East

County: Umatilla

Date: August 21, 2001

Corner Designation: v-22

N.W. corner of N.E. 1/4, N.W. 1/4, Sec. 36

Previous Renewals/Surveys, etc.:

None

Monument(s) & Accessories Found (Condition & Source):

None

Monument Detail:

Monument Set (Procedures & Description):

5/8"x30" rebar with yellow cap stamped "Tomkins Surveying" set at proportioned position along North line of Section 36.

New Accessories:

- 1) Fence post and sign 0.5' West
- 2) 12" White Fir scribed "1/16 BT", sign attached bears N 41°W 13.0'
- 3) <sup>15"</sup>~~12"~~ White Fir scribed "1/16 BT", sign attached bears N 67°W 33.0'
- 4) Old fence corner 50' East and 20' South of corner.

Location & Comments:

Compass Declination:

19° East

Firm/Agency: Tomkins Land Surveying, Inc.


20 E. Poplar, Suite 204  
Walla Walla WA 99362

Party Chief: Paul Tomkins


Notes:

Witness: Josh Davin

Surveyor's Seal



*Paul W. Tomkins*



*renews 6-30-02  
8/22/01*

RECEIVED BY

Umatilla County Surveyor:

Date 8-01

Rec'd By RF

No. 01-132-C