


LAND CORNER RECORD

(Rectangular)

1. T 6S R 29E No. N-23 Cor. 1/4 Mer. W State Oregon N. F. Umatilla Dist. Ukiah 30

2. Corner Status



3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Corner is a post from which:  
 a 30" Pine Brs. N. 40°W. 32 lks. (22")  
 a 30" Pine Brs. S. 60°W. 28 lks.  
 ● see mon. file, Brass Cap.

5. Investigation Notes:

Sec. 13 B.T., 22" Ponderosa Pine, painted red stripe on tree, form 54-3 present, medium vigorous.  
 Sec. 24 B.T., no evidence found, old stumps at possible location.  
 Corner post not located.

7. Photo Identification

Photo No. \_\_\_\_\_  
 Ident. By: KRJ

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Field Book No. \_\_\_\_\_  
 Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_  
 Needs Verif. \_\_\_\_\_ Monument No  
 Re-estab. X Survey \_\_\_\_\_  
 Land Status Public Domain

6. Signed K.R. Johnson Title Forester Date 6-8-65

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By \_\_\_\_\_ Title \_\_\_\_\_

License \_\_\_\_\_ Agency \_\_\_\_\_ Date \_\_\_\_\_

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_

(Agency)

(Date)

(City)

(County)

(State)

14. Remarks:

N-23