

USDA-FOREST SERVICE

Index			CORNER RECORD (SEARCH)	Tract or	Cor.
File No. A-14			Ref. FSM 7151.4	Survey No	No.
T6S	R30E	E.D.	North Fork John Day	County	Umatilla
Merid.	Willamette	N.F.	Umatilla	State	Oregon

x-----1-----1

Corner Diagram 1 Describe corner monument found

T6S R30E 1 Steel pipe extending 10" above the ground with a 2 1/2" brass cap stamped as shown in the diagram.

W1/16 S3 1

1977 1

PLS 933 1

x-----1-----x

Photo Identification Data 1 Describe bearing trees or other official accessories found

Photo No. 1 A 8" Ponderosa Pine bears S33°28'E, 13.5' with healed scribe.

filed at 1 A 11' Ponderosa Pine bears S22°55'W, 39.6' with healed scribe.

Object Ident. 1

Ident. by 1

Signature 1

x-----1-----x

Plane Coordinate Position Data 1 Describe corner location relative to near-by features, also how to reach corner

State Zone 1 From the junction of roads 5312 and 5320, follow road 5320 east 1.2 miles to road 5320105. Follow road 5320105 south 0.7 miles to an east-west fence. Follow the fence west approximately 300' to the corner which lies just south of the fence.

X 1

Y 1

Estab. by 1

Agency 1

x-----1-----x

Signature	Title	Division	Headquarters	Date	7100.52
<i>David L. Hadlock</i>	Land Surveyor		Pendleton, OR	June 1988	

CORNER RECORD (PERPETUATION)

X \_\_\_\_\_ X  
 Monument: Describe new monument set, or work done to preserve existing monument

TRUE CORNER POINT

Set steel guard post 5' west of the monument and attached Forest Service Land Survey Monument and Property Boundary signs.

X \_\_\_\_\_ X  
 Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

Repainted blazes and bands on trees red. Attached Forest Service Land Survey Monument signs to trees.

X \_\_\_\_\_ X  
 Work done by David L. Haddock Title Land Surveyor Date Nov 1988 State Registration No.  
 Certified cor. record prepared? yes no x Filed at or Agency 852  
 Date

X \_\_\_\_\_ X  
 REMARKS

X \_\_\_\_\_ X  
 Index File No. A-14 T.69. R.30E. N. Willamette Tract or Survey No. Cor.

USDA-FOREST SERVICE

Index  
File No. A-14  
T 6S R. 30E  
Merid. Willardette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah County Umatilla Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_  
N.F. Umatilla State Oregon

CORNER DIAGRAM



T. 5S., R. 30E.

W 1/16 S.3

T. 6S., R. 30E.

DESCRIBE CORNER MONUMENT FOUND

None

*Set brass cap*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From the intersection of U.S. Forest Road 419N and 537N, go East about 2 miles to a fence, then West along fence about 51.8 chns. to the corner.

*Signature*  
*David H. Kaler*

Title COOPER Division OPLS Headquarters 933

Date 7-77

7100-52-(3/68)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" iron pipe with brass cap  
 Pipe is 15" in ground

T. 6S., R. 30E.

W 1/16 S.3

Stamped as shown:

1977  
 PLS 933

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 11" pine bears S. 22°55' W. 39.6 ft.

A 8" pine bears S. 33°28' E. 13.5 ft.

Set steel fence post 3' East of Brass cap w/sign

Painted red band around bearing tree w/sign

Work Done By T. Hamby Title Party Chief Date 6/23/77 State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes  No \_\_\_\_\_ Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

12

13