

USDA-FOREST SERVICE

Index

File No. A-15

T6S R30E

Merid. Willamette

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

R.D. North Fork John Day

N.F. Umatilla

Tract or

Survey No

County Umatilla

State Oregon

Cor.

No.

x-----1-----1

Corner Diagram T5S R30E

1/4 S3

T6S R30E

1977

PLS 933

1 Describe corner monument found
1 Steel pipe extending 4" above the ground with a 2 1/2" brass cap stamped as
1 shown in the diagram.

1

1

1

1

x-----x

Photo Identification Data

Photo No.

filed at

Object Ident.

Ident. by

Signature

1 Describe bearing trees or other official accessories found
1 A 11" Douglas Fir bears S85°34'E, 33.6' with healed scribe.
1 A 11" Douglas Fir bears S29°34'W, 18.3' with healed scribe.

1

1

1

x-----x

Plane Coordinate Position Data

State

Zone

X

Y

Estab. by

Agency

1 Describe corner location relative to near-by features, also how to reach corner
1 From the junction of roads 5312 and 5320, follow road 5320 east 1.2 mile to road
1 5320105. Follow road 5320105 south 0.7 mile to an east-west fence line. Follow
1 the fence east approximately 800' through a clearcut and into the timber on the
1 other side. The corner is located just south of the fence.

1

x-----x

Signature

Title

Division

Headquarters

Date

7100.52

David L Haddock

Land Surveyor

Pendleton, OR

June 1988

USDA-FOREST SERVICE

Index
File No. A-15

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

T 6S. R. 30

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



T. 5S., R. 30E.

1/4 S. 3

T. 6S., R. 30E.

DESCRIBE CORNER MONUMENT FOUND

None

Set brass cap.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From the intersection of U.S. Forest roads 419N and 537N, go East about 2 miles to a fence, then West along fence 30 chns. to corner.

Signature
David H. K. Co.

Title

Division

Headquarters

Date

7100-52-(3/68)

OPLS

933

7-77

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" iron pipe with brass cap.

Pipe is 27" in ground.

Stamped:

T. 5S., R. 30E.,

T. 5.3

T. 6S., R. 30E.

T. 6S. 1977 30E.

PLS 933

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 11" fir bears S. 85°34' E. 33.6 ft.

A 11" fir bears S. 29°34' W. 18.3 ft.

Set steel post 4 ft. East of corner w/sign.

Painted red band around trees w/sign.

10

Work Done By. T. Hamby Title Party Chief Date 6/23/77 State Registration No. _____ or Agency _____Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13