

USDA-FOREST SERVICE

Index

File No. A-20

T6S

R30E

Merid. Willamette

P.D.

N.F.

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

North Fork John Day

Umatilla

Tract or

Survey No

County Umatilla

State Oregon

Cor.

No.

x

Corner Diagram T6S R30E

E1/16

CC 52

E

1977

x

PLS 933

Photo Identification Data

Photo No.

filed at

Object Ident.

Ident. by

Signature

x

Plane Coordinate Position Data

State

Zone

X

Y

Estab. by

Agency

x

Signature

Title

Division

Headquarters

Date

David L. Haddock

Land Surveyor

Pendleton, OR

June 1988

7100.52

1 Describe corner monument found

1 Steel pipe extending 15" above the ground with a 2 1/2" brass cap stamped as shown in the diagram, in a mound of stone.

1

1

1

1

1 Describe bearing trees or other official accessories found

1 A 10" White Fir bears S33°47'E, 54.9' with healed scribe.

1 A 10" White Fir bears S39°17'W, 25.6' with healed scribe.

1

1

1

1

1 Describe corner location relative to near-by features, also how to reach corner

1 From the junction of roads 5312 and 5320, follow 5320 east 1.6 miles to road

1 5320110. Then follow road 5320110 east 1.4 miles and follow a logging spur road

1 south through an open area to an east-west fence. Follow the fence west

1 approximately 900' to the corner.

1

1

CORNER RECORD (PERPETUATION)

X-----X  
 Monument: Describe new monument set, or work done to preserve existing monument

Set steel guard post 5' east of the <sup>TRUE CORNER POINT</sup> monument and attached Forest Service Land Survey Monument and Property Boundary signs.

X-----X  
 Accessories: Describe new RT's witness objects etc. established, or work done to preserve existing evidence

Repainted red bands around trees. Attached Forest Service Land Survey Monument signs to trees.

X-----X  
 Work done by David L. Haddock Title Land Surveyor Date Nov 1988 State Registration No. 852  
 Certified cor. record prepared? yes no x Filed at Date

X-----X  
 REMARKS

X-----X  
 Index File No. A-20 T.6S. R.30E. M. Willamette Tract or Survey No Cor.

USDA-FOREST SERVICE

Index File No. A-20

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. \_\_\_\_\_ No. \_\_\_\_\_

T 6S. R. 30E.

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



T. 5S., R. 30E.

E 1/16

CC S.2  
E.

T. 6S., R. 30E. 6

DESCRIBE CORNER MONUMENT FOUND

None

Set brass cap

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature* \_\_\_\_\_ 7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Gulliford crossing sign, go East about 1.1 miles, then walk South 7.6 chns. to fence and corner.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency* \_\_\_\_\_ 8

Signature  
*David H. Kulin*

Title

Division

Headquarters

Date

7100-52-(3/68)

OPLS

933

7-77

5

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" iron pipe with brass cap.  
 Pipe is 15" in ground.  
 Mound of stones to cap.

T. 6S., R. 30E.  
 E. 1/16

CC S.2

1977

PLS 933

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 10" fir bears S. 33°47' E. 54.9 ft.  
 A 10" fir bears S. 39°17' W. 25.6 ft.

Set steel fence post 3.5 ft. East of corner w/sign.  
 Painted red band around BT trees w/sign.

10

Work Done By T. Hamby Title Party Chief Date 6/23/77 State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes  No \_\_\_\_\_ Filed At: \_\_\_\_\_ Date \_\_\_\_\_ 11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13