

USDA-FOREST SERVICE

Index File No. B-18

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ No. _____

T 6S. R. 30E. R.D. Ukiah County Umatilla

Merid. Willamette N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None
Set brass cap

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From intersection of U.S. Forest Road 419N and 537N, go East by South about 2.6 miles, then turn left and go East 0.2 miles, then walk 6.00 chns. Northwest to corner.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature
David H. Kibler

Title _____ Division OPLS Headquarters 933

Date 7-77

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

GPO 902-679

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NW 1/16 S.2

Set 2½" x 30" iron pipe with brass cap.
 Pipe is 14 inches in ground.
 Mound of stones to cap.

1977
 PLS 933

Stamped:

ACCESSORIES : DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 11" pine bears N. 85°43' E. 21.3 ft.

A 13" fir bears N. 65°57' W. 41.6 ft.

Set steel fence post 3 ft. North of corner w/sign.
 Painted red band around BT trees w/sign.

Work Done By T. Hamby Title Party Chief Date 6/23/77 State Registration No. _____
 or Agency _____

Certified Cor. Record Prepared ? Yes No _____ Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12 13