

USDA-FOREST SERVICE

Index File No. E-2

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ No. 1/16 Cor


T 6S R. 30E

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

PLS
Division

346
Headquarters

9/79
Date

7100-52-(3/68)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is less than 100' North of unnumbered road and is visible from same.

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 32" X 2" flanged iron pipe with brass cap marked:

T6S R30E
W 1/16 S6
S7
1979
PLS 346

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Douglas Fir, 10" Dia., BRS. N14⁰E., 12.4 Ft. Distance.
Douglas Fir, 14" Dia., BRS. S28¹⁰W., 54.2 Ft. Distance.
6' Iron Fence Post with "Survey Monument" sign within 5' of Corner.Work Done By Wayne O. Harris Title PLS Date 9/79 State Registration No. 346
or AgencyCertified Cor. Record Prepared? YES ~~XNXX~~ Filed At: Umatilla Co. Surveyor Office Date

REMARKS

Index File No: E-2 T. 6S R30E W. M. Tract or Surv. No.Cor. W1/16 6
7
13