

USDA-FOREST SERVICE

Index
File No. 5-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ No. _____


T 6S R. 30E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

28"x15"x6" BASALT STONE IN A MOUND OF STONES

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

STUMP-HOLE N20W 47.5'

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS ON WEST SIDE OF CREEK NEAR OLD ROAD.
THERE IS A LOCATION TAG ON ROAD APX. 100' EAST
OF CORNER ON OLD ROAD.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

M.D. Davis
Signature

Title _____ Division _____ Headquarters _____ Date _____

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2" X 30" IRON PIPE WITH A BRASS-OAP MARKED:

T6S R30E

THE CORNER MONUMENT IS SET IN A MOUND OF STONES.

1/4 S11

1/4 S14

1978

PLS 346

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

14" FIR S33E 34.5' MARKED: 1/4 S14 BT

12" PINE N34W 37.7' MARKED: 1/4 S11 BT

ALL BT'S HAVE A RED-PAINTED STRIPE, BEARING TREE TAGS, AND AN ATTENTION TAG, AND A BRASS WASHER STAMPED PLS 346 NAILED TO THE LOWER BLAZE.

THERE IS A STEEL FENCE POST NEAR THE CORNER.

10

Work Done By W. O. HARRIS Title _____ Date _____ State Registration No. PLS 346
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

13

Index
File No. J-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. J-19


T 6S R. 30E

R.D. Ukaih County _____

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



● Brass Cap 1978

DESCRIBE CORNER MONUMENT FOUND

28" X ~~26~~^{26 1/2} X 6" Basalt stone in mound of stone. Marked 1/4 on North face.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Evidence of stump hole and scraps of wood in proper location. for B.T.
Pilot Rock Lmbr. Co. location poster dated 1959 on 12" Pnd. Pine S80E approx. 40 ft.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is about 50 feet west of stream. There is a primitive road about 50 ft. east of stream.

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

T. HOLLAMON

ENG. TECH.

5/15/78

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Placed location poster on 16" Pond, Pine on edge of road approx. ^{75°}S50°W, 100 feet from corner.

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. _____

13