

Index J-21

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ No. _____

T 6S R. 30E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



T6S R30E

S11 | S12

S14 | S13

DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

36" PINE N62W 36.3' SCRIBING VISIBLE.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS ON WEST SIDE OF CREEK APX. 50' FROM OLD ROAD.

X *W.C. Davis*

Title _____ Division _____ Headquarters _____ Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2"x30" IRON PIPE WITH A BRASS-CAP MARKED:

T6S R30E
S11 S12
S14 S13
1978
PLS 346

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" FIR S38W 39.6' MARKED: T6S R30E S14 BT

22" FIR N74E 53.9' MARKED: T6S R30E S12 BT

16" FIR S66E 64.1' MARKED: T6S R30E S13 BT

ALL BT'S HAVE A RED-PAINTED STRIPE, BEARING TREE TAG, AND AN ATTENTION SIGN. THE NEW BT'S HAVE A BRASS WASHER STAMPED PLS 346 NAILED TO THE LOWER BLAZE. THERE IS A FENCE POST ON LINE NEAR THE CORNER.

Work Done By W.O. HARRIS Title _____ Date 9-6-78 State Registration No. PLS 346
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

12

13

USDA-FOREST SERVICE

Index File No. J-21

T 6S R. 30E

Merid. Willamette

2
CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or Survey No. _____

Cor. No. J-21

R.D. Ukiah County _____

N.F. Umatilla State Oregon

CORNER DIAGRAM



● Brass Cap 1978

DESCRIBE CORNER MONUMENT FOUND

12" L.P. Pine with blazes and large X.
Old location poster indicates it is the corner. (original corner was stone in ground)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 36" Pond. Pine bears approx N62°W, Approx. 37 ft. scribing visible.
Other B.T. was probably destroyed by road and stone mound probably scattered.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

12" L.P. Pine is about 20' west of old road and about 60' West of Brook.

Signature

T. HOLLAMAN

Title

ENG. TECH

Division

Headquarters

Date

5/15/78

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Placed blank location poster on the 12" L.P. Pine to attract attention. location poster on other side has information. Placed blank B.T. tag on attention poster on the B.T.

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At _____ Date _____

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor.

13