

USDA-FOREST SERVICE

Index

File No. R-13

T6S R32E

Merid. Willamette

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

North Fork John Day

Umatilla

Tract or

Survey No

County Umatilla

State Oregon

Cor.

No.

x

1

1

Corner Diagram

T6S R32E

S21 } S22

x-----

S28 } S27

1968

1 Describe corner monument found

1 Standard BLM brass cap stamped as shown in the corner diagram in a mound of stone.

1

1

1

x

1

x

Photo Identification Data

Photo No. 280-242

filed at Pendleton, OR

Object Ident. Bearing Trees

Ident. by David L. Haddock

Signature

1 Describe bearing trees or other official accessories found

1 A 31" Ponderosa Pine bears S11 W, 18.6'.

1 A 23" Ponderosa Pine bears N25 W, 18.6'.

1 A 27" Ponderosa Pine stump bears S15 E, 69'.

1 A 12" Ponderosa Pine bears N83 E, 15.8'. A 12" Ponderosa Pine bears S60 W, 48.9'.

1 A 13" Ponderosa Pine bears S44 W, 56.8'.

x

1

x

Plane Coordinate Position Data

State Zone

X

Y

Estab. by

Agency

1 Describe corner location relative to near-by features, also how to reach corner

1 From the junction of roads 55 and 5506, follow road 55 0.5 miles west to road

1 063. Follow this road 0.6 miles north to the N1/16 corner of sections 27 and 28.

1 From this corner, follow the posted property boundary north 1300' to the section

1 corner which is in the bottom of a ravine about 10' west of the stream bed.

1

x

1

x

Signature

Title

Division

Headquarters

Date

7100.52

David L. Haddock

Land Surveyor

Pendleton, OR

July 1988

CORNER RECORD (PERPETUATION)

X _____ X
 Monument: Describe new monument set, or work done to preserve existing monument

Set steel guard post 5' south of the monument and attached Forest Service Land Survey Monument and Property Boundary signs.

X _____ X
 Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

Made bands around trees and painted bands and scribe blazes red. Attached Forest Service Land Survey Monument and Bearing Tree signs to the trees. Did the same to the stump.

X _____ X

Work done by	David L. Haddock	Title	Land Surveyor	Date	July 1988	State Registration No.	
Certified cor. record prepared?	yes		no x	Filed at		or Agency	852
						Date	


X _____ X
 REMARKS

X _____ X

LAND CORNER RECORD

1. T. 6S R. 32E No. R13 Cor. Sec Mer. W State Oregon ^(Rectangular) N. F. Umatilla Dist. Dale

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

5. Investigation Notes:

See attached form 874-9

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument NO

Re-estab. Survey _____

Land Status _____

6. Signed _____ Title _____ Date _____

PERPETUATION RECORD

10. Monument:

Page

Page

(State)

T. 6 S. R. 32 E. R-13

(Make sketch of topography near Corner and show section line markers thus "X")

<p>Sec. 33</p> <p>DO NOT REMOVE THIS TO BE A RECORD OF THE OFFICE CORNER;</p> <p>SECTION LINE MARKER BETWEEN SECS. 33 AND 34</p> <p>33</p> <p>Sec.</p>	<p>Sec. 34</p> <p>SECTION LINE MARKER BETWEEN SECS. 34 AND 35</p> <p>34</p> <p>Sec.</p>
--	---

Metal Location Poster is on a WALNUT tree 16 inches diameter, on the W side of 11 1/2 from which this Corner bears S 85° E 25 Chains. (Bearing) (Distance)

Section line marker between Secs. 33 and 34 is on the W side of the road (Name of road, trail, etc.) located 1/2 chains E. W. N. E. from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

33 34 35

Sec. CORNER COMMON TO SECTIONS

L. 33 B. 33 M.G.L.

CORNERS OF THE PUBLIC SURVEY


T. 6 S. R. 32 E. - R-13 - SEC. 31

LAND CORNER RECORD

5680-2

1. T 6S R 32E No. R-13 Cor. Sec Mer. W State Oregon (Rectangular) N. F. UMATILLA Dist. Dal.

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:
Consists of a stone in place, condition O.K., 6" above ground
Brass Cap! see Mon. File.

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument NO

Re-estab. Survey _____

Land Status _____

5. Investigation Notes:

BT's
 16" PP bearing N. 25°W. .28
 22" PP bearing S. 11°W. .27
 24" PP bearing S. 15°E. 1.04

Metal poster on WT 16" dia. from which this cor. bears S. 25°E. .28 ch.

6. Signed A.E.B. Title D.R. Date Feb. 1952

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date)

(City)

(County)

(State)

14. Remarks:

R-13