

USDA-FOREST SERVICE

Index

File No. 8-15

T&S R32E

Merid. Willamette

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

North Fork John Day

Umatilla

Tract or

Survey No

County Umatilla

State Oregon

Cor.

No.

x ----- 1

Corner Diagram C 1 Describe corner monument found  
 11 1 Standard BLM brass cap stamped as shown in the corner diagram in a mound  
 CN--|S27 1 of stone.  
 161 1  
 C 1  
 196B 1

x ----- x

Photo Identification Data 1 Describe bearing trees or other official accessories found  
 Photo No. 1 A 9" Ponderosa Pine bears S41 E, 12.5'.  
 filed at 1 A 12" Ponderosa Pine bears S85 W, 49.4'.  
 Object Ident. 1  
 Ident. by 1  
 Signature 1

x ----- x

Plane Coordinate Position Data 1 Describe corner location relative to near-by features, also how to reach corner  
 State Zone 1 From the junction of roads 55 and 5506, follow road 55 0.3 miles east to road  
 X 1 070. Follow this road 0.2 miles north to road 073. Follow this road north 0.2  
 Y 1 miles to the corner which is easily visible about 100' west of the road.  
 Estab. by 1  
 Agency 1

x ----- x

Signature Title Division Headquarters Date 7100.52  
*David L. Hadlock* Land Surveyor Pendleton, OR July 1988

CORNER RECORD (PERPETUATION)

X \_\_\_\_\_ X  
Monument: Describe new monument set, or work done to preserve existing monument

None

X \_\_\_\_\_ X  
Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

Painted bands and scribe blazes red.

X _____ X								
Work done by	David L. Haddock	Title	Land Surveyor	Date	July 1988	State Registration No.		
Certified cor. record prepared?	yes		no x	Filed at		or Agency	852	
X _____ X						Date		

REMARKS

X \_\_\_\_\_ X  
Index File No. S-15 T.6S. R.32E. M. Willamette Tract or Survey No Cor.

USDA-FOREST SERVICE

Index  
File No. S-15

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_

T 68 R. 32E

R.D. N. Fk. J. Day County Umatilla

Merid. W.M.

N.F. Umatilla State Or.

CORNER DIAGRAM



CNW 1/16 S27

DESCRIBE CORNER MONUMENT FOUND

2 1/2" iron pipe with brass cap mkd. in stone mound.

N1/16  
C  
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

P. Pine, 9", S41°E, 12.5', with scribing visible  
P. Pine, 12", S85°W, 49.2' " " "

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_

Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on NW slope, west of rd. (see map).  
Bts visible from rd.

Signature  
*F. P. Munro*

Title  
*L.S.*

Division

Headquarters

Date  
*11/19/86*

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BTs have blaze and 6" band painted red, BT tags and "Land Survey Monument" signs. 6' steel fence post with "Land Survey Monument" sign within 5' of the corner.

10

Work Done By F.S. Munro Title L.S. Date 11/1/86 State Registration No. or Agency 1832

Certified Cor. Record Prepared ? Yes No  Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

12

Index File No. S-15 T. 68 R. 32E M. W.M. Tract or Surv. No. \_\_\_\_\_ Cor. \_\_\_\_\_