

USDA-FOREST SERVICE

Index File No. S-25

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. _____


T 6S R 32E

R.D. NORTH FORK JOHN DAY County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

BLM BRASS CAPPED IRON PIPE 3" ABOVE GROUND IN A M.D.S.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

13" FIR SNAG - BURNT OUT BLAZE - BEARS 570° E, 167 FT.

9" FIR SNAG - HEALED BLAZE - BEARS 530° W, 97 FT

12" W. LARCH SNAG - HEALED BLAZE - BEARS 567° 30' E, 912 FT.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Dennis L. Hayford

PLS 1636 MARCH 26, 1997

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES : DESCRIBE NEW BT/WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5/8" rebar w/ Brass washer m/kd "PLS 1636 530"
BEARS S79° E, 68 ± ft.

5/8" rebar w/washer m/kd "PLS 1636 525" bears
S4° W, 77 ± ft.

Work Done By D. GAYLORD Title FOREST L.S. Date 3/26/97 State Registration No. 1636
or Agency

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA COUNTY SURVEYOR Date APRIL 1997

REMARKS

Index File No. 5-25 T. T6S R. 2 M. WILL Tract or Surv. No. Cor. 11

USDA-FOREST SERVICE

Index
File No. 8-25

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____


T 6S R. 32E

R.D. N. Fr. J. Day County Umatilla

Merid. W.M.

N.F. Umatilla State Or.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2 1/2" iron pipe with brass cap mkd.

in a stone mound.

N1/16
825/830
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

W. Fir, 8" dbh, 8310W, 9.9'

D. Fir, 13" dbh, 8700E, 16.5' (This tree is dying.)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature
F. L. Munro

Title
L.S.

Division

Headquarters

Date
11/19/86

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None..

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Tamarack, 12", S66 3/4°E, 91.7', mkd.: NU/16 S30 BT
 BTs have blaze and 6" band painted red, BT tags and "Land Survey Monument" signs..
 New BT has alum. "PLS 1832" washer nailed to bottom of blaze.
 6' steel fence post with "Land Survey Monument" sign within 5' of the corner..

Work Done By F.S. Munro Title L.S. Date 11/30/86 State Registration No. 1832
 or Agency _____
 Certified Cor. Record Prepared ? Yes No Filed At: Umatilla Co. Surveyor Date _____

REMARKS

Index File No. S-25 T. 6S R. 32E M. W.M. Tract or Surv. No. _____ Cor. _____