

USDA-FOREST SERVICE

Index File No. U-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

T 68 R. 32E

R.D. N. Fk. J. Day County Umatilla

Tract or Survey No. _____ Cor. No. _____

Merid. W.M.

N.F. Umatilla State Or.

CORNER DIAGRAM



S1/16
S28/S27

DESCRIBE CORNER MONUMENT FOUND

2 1/2" iron pipe with brass cap mid. in stone mound.

S1/16
S28/S27
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

D. Fir, 7", N66°E, 23.1', with healed blaze.
D. Fir, 8", S48°W, 15.8', with scribing visible.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on NW slope in thick second growth fir. From K tag on 5505 rd. follow posted line 2145' west.

Signature
F.L. Munro

Title
L.S.

Division

Headquarters

Date
11/19/86

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None..

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BTs have blaze and 6" band painted red, BT tags and "Land Survey Monument" signs. 6' steel fence post with "Land Survey Monument" sign within 5' of the corner..

Work Done By F.S. Munro Title L.S. Date 11/4/86 State Registration No. 1832
or Agency
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. U-13 T. 68 R. 32E M. W.M. Tract or Surv. No. _____ Cor. _____