

INDEX

FILE NO. V-7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Cor.

T. 6 S R. 32 E R.D. North Fork John DayCounty UmatillaNo. Merid. WillametteN.F. UMATILLAState Oregon

CORNER DIAGRAM

T65 R32E

1 DESCRIBE CORNER MONUMENT FOUND

1 BLM DC

S29

1 A standard BLM monument stamped as shown in the diagram.

1

1/4----

1

N

S32

1

1

1968

1

1

1 DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1 A 20" dbh Western Larch bears S79 1/2"W, 7.3' with visible scribe.

PHOTO IDENTIFICATION DATA

1 A 12" Douglas Fir bears N24 1/2"E, 19.6' with healed blaze.

Photo No.

1 A 14" dbh Douglas Fir bears S58 1/2"E, 19.9' with healed blaze.

Filed at.

1

Object Ident.

1

Ident. By

1

Signature

1

PLANE COORDINATE POSITION DATA

1 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

State Zone

1 From Highway 395, follow FSR 55 6.5 miles to FSR 5505. Follow FSR 5505 0.5 mile to

X

1 FSR5505020. Then follow FSR5505020 1.1 mile to a junction. Go right 0.25 mile to a junction.

Y

1 Go right 0.3 mile to a junction. Go left 0.4 mile to a junction. Go right downhill 0.8 mile

Estab. By

1 to a junction. Go right and follow the road along the river 0.4 mile to a slide. Continue on

Agency

1 the road 0.2 mile to the corner which is on the north bank of the river.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

David L. Haddock

Surveyor

Pendleton, OR

6-02-94

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Cleared brush and debris away from corner.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set new bearing tree.

A 8" dbh Douglas Fir bears S42 1/2°W, 39.6' scribed 1/4 S32 BT.

An aluminum washer stamped RLS 852 is nailed between the letters B and T on each new tree. BT and LSM signs are attached to each bearing tree and 6" red bands painted around them.

10

Work Done By. David L. Haddock Title Land Surveyor Date 5-27-94 State Registration No. _____
or Agency PLS 852
Certified Cor. Record Prepared? x Yes No Filed At: Umatilla County Surveyor Date 5-94 11

REMARKS

12

Index File No. V-7 T. 6 S. R. 32 E. M. Willamette Tract or Surv. No. _____ Cor. _____ 13

USDA-FOREST SERVICE

Index
File No. V-7
T 6S R. R32E
Merid. Willamette


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. _____

R.D. NORTH FORK JOHN DAY County UMATILLA
N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

BLM BRASS CAP MKD. T 6S R 32 E
SET ON 2 1/2" IRON PIPE 1/4 529
IN A MOUND OF STONES 532
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Fir, 12" diam, BEARS N. 24° 28' E., 19.6 FT (RECORD N. 24° E., 29 1/2 lks) WITH HEALED BLAZE
A Fir, 11" diam, BEARS S 58° 23' E., 19.9 FT (RECORD S 58° E., 30 lks) WITH HEALED BLAZE
A Birch, 20" diam, BEARS S 79° 32' W., 7.3 FT (RECORD S 79° W., 11 lks) WITH PARTIALLY HEALED BLAZE

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LOCATED 50 FT. NORTH OF ABANDONED ROAD LAYING SOUTHSIDE OF THE NORTH FORK JOHN DAY RIVER.

TAKE LOGGING ROAD 0.1 MILE INTO N 1/2 OF NE 1/4 S. 32. WHERE ROAD FORKS FOLLOW ABANDONED RIGHT HAND ROUTE 0.4 MILE TO CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

10/90

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

CLEARED BRUSH AND DEBRIS FROM AROUND CORNER AND RESET MOUND OF STONE

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

ATTACHED USFS SIGNS 54-3 AND 54-9 TO ALL BT'S

PAINTED 6" RED BAND AROUND ALL BT'S

SET GUARD POST 5 FT EAST OF CORNER WITH 54-2 AND 54-9 SIGNS ATTACHED

10

Work Done By: Guy Streamer Title LAND SURVEYOR Date 11/80 State Registration No. or Agency 1341 - GUY STREAMER

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA COUNTY SURVEYOR Date 2/96

11

REMARKS

WITNESS: KEN BATES
SCOTT KRICKA

12

Index File No. V-7 T. 65 R. 32E M. WM Tract or Surv. No. Cor. 13

LAND CORNER RECORD

5680-2

1. T. 6S R. 32E No. 14-7 Cor. 14 Mer. W State Oregon (Rectangular) N. F. Umatilla Dist. Dale

2. Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: *Original corner consisted of a post from which a fir, 24" dia, bears N67°E, 59 lks, marked 1/4 S BT larch, 10" dia, bears S79°W, 11 lks, marked 1/4 S BT*

5. Investigation Notes: *Actual corner not found Found two B.T.'s*

<p><i>DF (on ground)</i></p> <p><i>24" dia</i></p> <p><i>N67°E - to tree</i></p> <p><i>59 lks.</i></p> <p><i>Scribing = 1/4 S BT</i></p>	<p><i>WL</i></p> <p><i>12" dia</i></p> <p><i>S79°W</i></p> <p><i>11 lks</i></p> <p><i>Scribing = 1/4 S BT</i></p>
--	---

See attached 874-9

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. Monument No
Re-estab. Survey
Land Status _____

6. Signed /s/ Jack Mounts Title For. Aid Date 2-5-54

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

License _____ Agency _____ Date _____

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks: