

Index File No. C-25


CORNER RECORD (SEARCH)

Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_

T 65 R. 32E R.D. UKiah County \_\_\_\_\_

Merid. \_\_\_\_\_ N.F. \_\_\_\_\_ State \_\_\_\_\_

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Brass Cap:

1/4  
T 65  
R 32E R 33E  
S 1156  
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

See monumentation file  
ok 1/84

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

Signature

J. Hollamon

Title

Division

Headquarters

Date

2/75

7100-52

REV. '65 5

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

9

**ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_ 11

**REMARKS**

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13

Index  
File No. C-1

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or Survey No. \_\_\_\_\_  
Cor. No. \_\_\_\_\_


T 6S R. 33E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set,  
2½ ins. diam., in a mound of stone  
3 ft. base, to top, with brass cap  
mkd:

U.S. Dept. of Interior  
Bureau of Land Management

R32E T6S R33E  
S1 | 1/4 S6  
1968 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

- A Ponderosa Pine, 25 ins. diam., bears N 12°E 9 lks. dist., with healed blaze. (Record, 5 lks.)
- A Ponderosa Pine stump, 18 ins. diam., bears S 37°W 42 lks. dist., with scribe marks 1/4 S BT visible on open and weathered blaze. (Record S 44°W)
- A Ponderosa Pine snag, 11 ins. diam., bears S 31°W 89 lks. dist., marked 1/4 S1 BT.

PHOTO IDENTIFICATION DATA

Photo No. 280-231  
Filed At. UMATILLA Nat. For  
Object Ident. DIRGEY  
Ident. By S. Jangley  
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_

Agency  
Signature S. Jangley

Title LS 1099 Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date 9-18-84 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 14" Ponderosa Pine, scribed "1/4 S 1 BT" on a double blaze bears N 89°W 77.0 feet, with brass washer marked "LS 1099" attached to lower blaze.

10

Work Done By Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency

Certified Cor. Record Prepared?  Yes  No Filed At UMATILLA Co. SURVEYOR Date 9-84

11

REMARKS

Staff Compass (Declination 20° East)  
Steel Tape  
Corner is located in gentle SE slope in a N-S fenceline.

12

Index File No. C-1 T. 6S R. 33E M. WILLANETTE Tract or Surv. No. Cor. 13