


T. 6 S. R. 33 E.
Merid. Willamette

R.D. North Fork John Day County Umatilla
N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found "X" on the top of a boulder on top of a ridge. The "X" is 1.5 feet from the southeasterly edge and 5.1 feet from the northeasterly edge of the boulder.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

8" Douglas Fir Snag, with charred scribes visible, N. 55 W., 11.2 feet.
8" Juniper Snag, with charred scribes visible, N. 59 E., 37.3 feet.

PHOTO IDENTIFICATION DATA

Photo No.
Filed At.
Object Ident.
Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State: Zone:
X:
Y:
Datum:

Signature
D. Gaylord

Title
Land Surveyor

Division

Headquarters
S.O.

Date
05/28/1997

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

At the exact center of the chiseled "X" on top of the boulder, I set a 2" diameter brass tablet with a 3" stem set in a drill hole and cemented in place. Cap is stamped "NFJD WB AP 455 PLS 1636 1997".

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5/8" X 24" iron rod, set 23" into the ground with 3/4" brass washer "PLS 1636 SE" attached at ground level, bears S. 17 1/2 E., 90.3 feet.
5/8" X 36" iron rod, set 35" into the ground with 3/4" brass washer "PLS 1636 SW" attached at ground level, bears S. 43 3/4 W., 60.4 feet.

Work Done By D. Gaylord Title Land Surveyor Date 05/28/1997 State Registration No. _____
or Agency _____
Certified Corner Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

USDA-FOREST SERVICE

Index
File No. _____

T 6S R. 33E

Merid. WILLAMETTE

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

R.D. NORTH FORK JOHN DAY County UMATILLA

N.F. UMATILLA State OREGON

NFSD WILD.
Tract or Survey No. NFSD UNIT Cor. No. 455

CORNER DIAGRAM



DESCRIBE CORNER, MONUMENT FOUND

N/A

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N/A

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature _____ Title _____ Division _____ Headquarters _____ Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MARKED "+" ON BOULDER 12 FT X 7 FT X 2 FT HIGH AT CORNER POINT. THE "+" IS 1.5 FT FROM SE EDGE & 5.1 FT FROM NE EDGE OF FLAT TOPPED BOULDER.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" DOUGLAS FIR N71°W, 11.3 FT.
 8" JUNIPER N42°E, 37.7 FT. BOTH BLAZED & SCRIBED "WB/455 BT" & HAVE A BRASS WASHER, 3/4" DIAM., NAILED FLUSH TO BLAZE & 54-3 & 54-9 SIGNS ATTACHED. WASHERS ARE MARKED "PLS 1636"

Work Done By D. GAYLORD Title FOREST L.S. Date 6-26 89 State Registration No. 1636
 or Agency

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA CO. SURVEYOR Date 1989

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12