

USDA-FOREST SERVICE
Index
File No. **R-19**
T. 6 S. R. 34 E.
Merid. Willamette

CORNER RECORD (SEARCH)
(Ref. FSM 5151.4)


Tract or
Survey No.

Cor.
No.

R.D. North Fork John Day
N.F. Umatilla

County Umatilla
State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found a 2 1/2" aluminum pipe, with a 3 1/4" aluminum cap, set flush with the ground surrounded by a ring of stones.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

9" Western Larch, N. 73 E., 73.5 feet, with scribing visible on double blaze.
15" Douglas Fir, S. 22 E., 52.6 feet, with scribing visible on double blaze.
28" Douglas Fir, S. 74 W., 32.2 feet, with scribing visible on double blaze.
10" Lodgepole Pine, N. 20 W., 56.3 feet, with scribing visible on double blaze.

PHOTO IDENTIFICATION DATA

Photo No.
Filed At.
Object Ident.
Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State: Zone:

X:

Y:

Datum:

Signature

D. Schlaich

Title

Land Surveyor

Division

Headquarters

S.O.

Date

09/1997

FS-7100-52 (3/97)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By D. Schlaich Title Land Surveyor Date 09/1997 State Registration No. _____
or Agency _____
Certified Corner Record Prepared? Yes No Filed At: Umatilla County Surveyor's Office Date 11/1997

REMARKS

USDA-FOREST SERVICE

Index File No. R-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____


T 6S R. 34E

R.D. NORTH FORK JOHN DAY County UMATILLA

Merid. WILL

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

ORIG. CORNER STONE MK'd "1/4" ON NORTH of
"+" ON TOP

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ROOT HOLE of DECAYED LOG N23°E, 17.82'
ROOT HOLE S24°W, 13.2

3

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

4

Signature Dennis J. Taylor Title _____ Division PLS 1636 Headquarters SO Date 9-1-93

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" ALUM PIPE W/ 3/4" CAP MKD AS SHOWN IN DIAGRAM.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 8" W. LARCH N71°E, 73.5 FT.

A 14" D-FIR S22°E, 52.6 "

A 11" LODGEPOLE PINE N22°W, 56.8 FT

A 27" D-FIR S74°W, 32.9 FT

Work Done By D. GAYLORD Title _____ Date 9-1-93 State Registration No. 1636 or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA CO. Date 9-29-93

REMARKS

Index File No. T. 65 R. 34E M. _____ Tract or Surv. No. _____ Cor. _____

R-19

9

10

11

12

13