

USDA-FOREST SERVICE

Index
 File No. C21
 T 7S R. 31E
 Merid. Willamette


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
 Survey No. _____ Cor.
 No. _____

R.D. N.F. John Day County Grant
 N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is 200 feet, more or less, South of USFS housi area, and 200 feet East Snake Creek.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature
Will R. Webb

Title PLS Division _____

Headquarters Pendleton, OR

Date 1/19/94 100-52-(3,68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" aluminum cap on 2 1/2" X 30" aluminum pipe, 24" in ground with mound of stone and earth to cap, marked as shown in corner diagram. Attached sign 54-9 to steel fence post, set 4.0 feet North of monument.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 18" ponderosa pine bears N26°W- 47.4 feet, scribed: 1/4 S2 BT
A 13" ponderosa pine bears S81°W- 34.6 feet, scribed: 1/4 S2 BT
A 12" ponderosa pine bears S45°E- 23.6 feet, scribed: 1/4 S1 BT
A 10" ponderosa pine bears N40°E- 21.7 feet, scribed: 1/4 S1 BT
Bearing trees have brass washer stamped 'PLS 1106' nailed to the face of the blaze, attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

Work Done By. WR Wells Title PLS Date 8/23/93 State Registration No. PLS 1106
or Agency
Certified Cor. Record Prepared? Yes No Filed At: GRANT CO. SURVEYOR'S OFFICE Date 1/94

REMARKS

This corner was reestablished as part of a USFS contract.

USDA-FOREST SERVICE

Index
File No. C-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____


T 7S R. 31E

R.D. DALE County GRANT

Merid. WILL

N.F. UMATILLA State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE - FOUND STONE OF RECORD SIZE IN
FENCE LINE, NO MARKINGS VISIBLE,

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Dwight Bartleson
Signature

Title

Division

Headquarters

Date

C.E. Tech. S.O.

11/18/80

7100-52 (3,68)

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ **Title** _____ **Date** _____ **State Registration No. or Agency** _____

Certified Cor. Record Prepared ? Yes No **Filed At:** _____ **Date** _____

REMARKS

Index File No. **T.** **R.** **M.** **Tract or Surv. No.** **Cor.**